



NOTIFICATION

This report contains short preliminary information about an accident in Switzerland without pretension to completeness and without conclusions. An investigation is in progress by the Swiss Aircraft Accident Investigation Bureau.

Place, date and time: Samedan LSZS, 12 February 2009, 15:14 UTC

Aircraft:

Registration Mark: VP-BAF
Type: Dassault Falcon 100
Operator: Laret Aviation Limited, Clarendon House, 2 Church Street
Hamilton HM 11, Bermuda
Owner: Laret Aviation Limited, Clarendon House, 2 Church Street
Hamilton HM 11, Bermuda

Pilot: 2

Passengers: 1

Flight:

Flight rules: VFR
Type of operation: Private
Point and Time of departure: LOWW, 14:06 UTC
Point of landing: Samedan LSZS

Damage:

Crew: Fatally injured
Passengers: Seriously injured
Thirds: None
Aircraft: Destroyed
Ground: Some fuel leaked on ground (runway)

Short description of the accident:

Aircraft touched down left of centreline with the right wing first, then with right main gear. The aircraft drifted to the left and touched with the left wing a snow wall at the runway edge. The aircraft nose hit the snow wall frontally. The aircraft turned to the left and broke into two parts.